

Seznam souřadnic:

Číslo	Poloha X	Poloha Y
10001	-551416.72	-1113220.2900
10002	-551478.74	-1113207.4500
10003	-551489.91	-1113205.4900
10004	-551522.97	-1113202.0500
10005	-551531.05	-1113201.2100
10006	-551560.77	-1113198.1500
10007	-551580.43	-1113192.4500
10008	-551594.26	-1113185.5800
10009	-551605.85	-1113183.5900
10010	-551614.17	-1113183.7643
10011	-551615.32	-1113173.7800
10012	-551615.82	-1113125.1500
10013	-551616.27	-1113080.4600
10014	-551616.84	-1113024.3600
10015	-551617.53	-1112956.4900
10016	-551618.12	-1112898.5700
10017	-551618.53	-1112857.5700
10018	-551618.75	-1112835.9900
10019	-551619.13	-1112799.7400
10020	-551619.49	-1112763.9100
10021	-551627.61	-1112737.3900
10022	-551642.72	-1112724.0300
10023	-551665.26	-1112710.7800
10024	-551732.53	-1112671.2300
10025	-551770.90	-1112654.6800
10026	-551797.78	-1112643.1000
10027	-551813.41	-1112636.3500
10028	-551816.30	-1112635.1100
10029	-551815.72	-1112634.4300
10030	-551819.51	-1112632.7000
10031	-551825.70	-1112629.9100
10032	-551822.35	-1112622.7273
10033	-551740.15	-1112658.5000
10034	-551705.14	-1112676.5448
10035	-551633.03	-1112719.9070
10036	-551611.17	-1112758.1546
10037	-551607.62	-1113155.8717
10038	-551584.26	-1113186.7108
10039	-551560.63	-1113193.5895
10040	-551540.56	-1113197.2920
10041	-551508.79	-1113199.8884
10042	-551486.61	-1113202.7476
10043	-551447.77	-1113209.6103
10044	-551425.86	-1113211.5333
10045	-551415.62	-1113211.5350
10046	-551821.20	-1112620.2300
10047	-551810.05	-1112624.7200

Číslo	Poloha X	Poloha Y
10048	-551727.94	-1112659.6800
10049	-551627.47	-1112718.8600
10050	-551611.77	-1112732.9800
10051	-551609.15	-1112744.7100
10052	-551607.86	-1112754.8600
10053	-551607.49	-1112790.3100
10054	-551606.78	-1112854.7200
10055	-551606.67	-1112864.8700
10056	-551606.61	-1112869.9800
10057	-551606.35	-1112894.6500
10058	-551606.02	-1112924.6200
10059	-551605.54	-1112969.5500
10060	-551605.42	-1112981.3700
10061	-551605.00	-1113019.4500
10062	-551604.87	-1113031.7400
10063	-551604.73	-1113044.2500
10064	-551604.60	-1113056.6300
10065	-551604.15	-1113096.1900
10066	-551604.03	-1113108.9900
10067	-551603.88	-1113121.9100
10068	-551603.74	-1113134.9000
10069	-551603.49	-1113158.0000
10070	-551596.65	-1113174.7000
10071	-551588.70	-1113179.0400
10072	-551577.01	-1113184.8200
10073	-551562.17	-1113188.5900
10074	-551547.09	-1113191.1900
10075	-551488.94	-1113197.5200
10076	-551464.84	-1113201.8400
10077	-551436.33	-1113205.8400
10078	-551423.36	-1113207.0700
10079	-551415.10	-1113207.4900