

Souprava: typ DPM

Zkouška podle ČSN EN ISO 22476-2

Měřil: Fajfr ml. Počet měř. úderů []: _____

Hloubka sondy [m]: 2.40

Datum zkoušky: 2.11.2016

Hlad. podz. vody [m]: nebyla zastižena

Y= 834 979.37

X= 1 041 882.48

Z= 505.06

Krok penetrování [m]: 0.10

Souř. systémy: JTSK / Balt

| Hloubka [m] | Počet úderů | | Qd [MPa] | Hl. [m] | Graf penetrace | | | | | | | | | | Geologická charakteristika | |
|----------------|-------------|------|-------------|------------|----------------|----|----|----|----|----|----|----|--|--|----------------------------|--|
| | měř. | red. | | | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 | | | | |
| 0.1 | 2 | | | | | | | | | | | | | | | |
| 0.2 | 2 | | | | | | | | | | | | | | | |
| 0.3 | 4 | | | | | | | | | | | | | | | |
| 0.4 | 3 | | | | | | | | | | | | | | | |
| 0.5 | 3 | | | | | | | | | | | | | | | |
| 0.6 | 4 | | | | | | | | | | | | | | | |
| 0.7 | 3 | | | | | | | | | | | | | | | |
| 0.8 | 3 | | | | | | | | | | | | | | | |
| 0.9 | 2 | | | | | | | | | | | | | | | |
| 1.0 | 4 | | | | | | | | | | | | | | | |
| 1.1 | 5 | | | | | | | | | | | | | | | |
| 1.2 | 6 | | | | | | | | | | | | | | | |
| 1.3 | 8 | | | | | | | | | | | | | | | |
| 1.4 | 10 | | | | | | | | | | | | | | | |
| 1.5 | 11 | | | | | | | | | | | | | | | |
| 1.6 | 12 | | | | | | | | | | | | | | | |
| 1.7 | 12 | | | | | | | | | | | | | | | |
| 1.8 | 12 | | | | | | | | | | | | | | | |
| 1.9 | 15 | | | | | | | | | | | | | | | |
| 2.0 | 17 | | | | | | | | | | | | | | | |
| 2.1 | 17 | | | | | | | | | | | | | | | |
| 2.2 | 16 | | | | | | | | | | | | | | | |
| 2.3 | 17 | | | | | | | | | | | | | | | |
| 2.4 | 22 | | | | | | | | | | | | | | | |