

Souprava: typ DPM

Zkouška podle ČSN EN ISO 22476-2

Hloubka sondy [m]: 2.00

Hlad.podz.vody [m]: nebyla zastižena

Krok penetrování [m]: 0.10

Měřil:

Fajfr ml.

Počet měř.úderů []: _____

Datum zkoušky: 2.11.2016

Y= 835 841.81

X= 1 042 146.10

Z= 507.82

Souř.systémy: JTSK / Balt

| Hloubka [m] | Počet úderů | | Qd [MPa] | Hl. [m] | Graf penetrace | | | | | | | | | | Geologická charakteristika | |
|----------------|-------------|------|-------------|------------|----------------|----|----|----|----|----|----|----|--|--|----------------------------|--|
| | měř. | red. | | | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 | | | | |
| 0.1 | 24 | | | | | | | | | | | | | | | |
| 0.2 | 48 | | | | | | | | | | | | | | | |
| 0.3 | 26 | | | | | | | | | | | | | | | |
| 0.4 | 13 | | | | | | | | | | | | | | | |
| 0.5 | 14 | | | | | | | | | | | | | | | |
| 0.6 | 18 | | | | | | | | | | | | | | | |
| 0.7 | 28 | | | | | | | | | | | | | | | |
| 0.8 | 9 | | | | | | | | | | | | | | | |
| 0.9 | 8 | | | | | | | | | | | | | | | |
| 1.0 | 7 | | | | | | | | | | | | | | | |
| 1.1 | 6 | | | | | | | | | | | | | | | |
| 1.2 | 8 | | | | | | | | | | | | | | | |
| 1.3 | 9 | | | | | | | | | | | | | | | |
| 1.4 | 10 | | | | | | | | | | | | | | | |
| 1.5 | 9 | | | | | | | | | | | | | | | |
| 1.6 | 11 | | | | | | | | | | | | | | | |
| 1.7 | 11 | | | | | | | | | | | | | | | |
| 1.8 | 13 | | | | | | | | | | | | | | | |
| 1.9 | 16 | | | | | | | | | | | | | | | |
| 2.0 | 17 | | | | | | | | | | | | | | | |