

Souprava: typ DPM

Zkouška podle ČSN EN ISO 22476-2

Hloubka sondy [m]: 2.00

Hlad.podz.vody [m]: nebyla zastižena

Krok penetrování [m]: 0.10

Měřil:

Fajfr ml.

Počet měř.úderů []: _____

Datum zkoušky: 2.11.2016

Y= 835 839.52

X= 1 042 030.10

Z= 518.34

Souř.systémy: JTSK / Balt

Hloubka [m]	Počet úderů		Qd [MPa]	Hl. [m]	Graf penetrace										Geologická charakteristika	
	měř.	red.			10	20	30	40	50	60	70	80				
0.1	5															
0.2	7															
0.3	7															
0.4	6															
0.5	5															
0.6	4															
0.7	5															
0.8	13															
0.9	13															
1.0	12															
1.1	12															
1.2	12															
1.3	12															
1.4	12															
1.5	13															
1.6	15															
1.7	11															
1.8	12															
1.9	14															
2.0	13															

Název akce: **NEČTINY - polní cesta HPC 1R**

Měřítko: 1:50

Zak. číslo: 16/562

Dokumentoval: RNDr. M. Fajfr

Vyhodnotil: RNDr. M. Fajfr

Zpracoval: RNDr. M. Fajfr

Příloha č.: **4.8**